

VISIBLE EMISSION NOTATIONS

	Contractor	C TO!				
Date of Inspection:					**************************************	i i
Shift: 1 st Shift or 2 nd Sh	nift T	lme:	,			
Visible Emission From Shaker	Visual Inspection NORMAL or ABNORMAL			Comments		
Visible Emission From Discharge Conveyor System	NOR					

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		_	
Inspector: PA	HOMO		£ 1	·
Date of Inspection:	112			3
Shift: 1 st Shift or 2 nd Sh	AFT TI	me: 5,00 Am		
White	Visual Inspection <u>NOR</u> MAL Or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	, the first desiration of the state of the s		
Visible Emission From Discharge Conveyor System	NOR		Milanini	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		_	
Inspector: PICK	PALON	10		
Date of Inspection:	112			1
Shift: 1 st Shift or 2 nd Sh	ZNO	me: 5100AM		
The Wait	Visual		Comments	
	Inspection <u>NOR</u> MAL			
	or ABNORMAL			
Visible Emission From Shaker	NOR	. На вичения постория поставления поставления поставления поставления поставления поставления поставления поста		
Visible Emission From				
Discharge Conveyor System	Nor	, was the second		•

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS				
Inspector: Smelko					
Date of Inspection:	0 10			3	
Shift: (1 st Shift) or 2 nd Sh	nift Ti	lme:		-	
E Properties	Visual Inspection <u>NOR</u> MAL Or ABNORMAL		Comments		
Visible Emission From Shaker	nor	other than the second s			
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Stoem	201			
Date of Inspection:	12/12			T _e
Shift: 1 st Shift or 2 nd Sh		me: @ SDO AM		
Unit	Visual		Comments	
	Inspection <u>NORMA</u> L			
	or <u>abn</u> ormal			
Visible Emission From Shaker	Nas	-		· · · · · · · · · · · · · · · · · · ·
Visible Emission From				
Discharge Conveyor System	NAR	O TOTAL CONTROL OF THE PARTY OF		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		_	
Inspector: Smc/Co				
Date of Inspection:	10. 11			1
OCOT	12,11			
Shift: (1st Shift) or 2nd Sh		me: 5:00		
#####################################	Visual		Comments	
	Inspection NORMAL			
	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	NOR	The second secon		
Visible Emission From				
Discharge Conveyor System	nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATION	ONS				
Inspector:	a			•	
Date of Inspection: 03	2			'n	
Shift: 1st Shift or 2nd Shift) Ti	me 500 ANU			
unit	Visual		Comments		
	Inspection <u>NOR</u> MAL or ABNORMAL				
Visible Emission From Shaker	Verz				
Visible Emission From Discharge Conveyor System	Vap	and the same of th			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			
Inspector: RICK PALOMC			
Date of Inspection: 9/4/12			ì
Shift: 1 st Shift or 2 ^{hd} Shift Time	5: 5:00 AM	<u>_</u>	
#Unit Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	**************************************		
Visible Emission From Discharge Conveyor System	*****COCCOMPANY		


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS						
Inspector: Smello							· ·
Date of Inspection:	1,12		,		J.		
Shift: (1 st Shift or 2 nd Sh	ift Ti	ime: 5,00					
aunit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL			Comments			
Visible Emission From,Shaker	NOR	**Company				*	
Visible Emission From Discharge Conveyer System	nor	- Additional and the second se		t e			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector:	ralomo	3		
Date of Inspection: 9/5	112			
Shift: 1 st Shift or 2 nd Sh	nift) Ti	me: 5:00 Am		
Sunt	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	NOR	Apparers to represent him the objection in state seathful distribution distribution.		
Visible Emission From Discharge Conveyor System	NOR	**************************************		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS

Inspector: Smell O Date of Inspection: Sept OS (2) Shift: (st Shift or 2 to Shift Time: Simple of Shift Time: Simple of Shift Or 2 to Shift Or 2 to Shift Or Or Shift Or	AISIDE EINISSION NOIN	ATIONS					
Shift: 1st Shift or 2nd Shift Time: Shift: 1st Shift Time: Shift: 1st Shift or 2nd Shift Time: Shift: 1st Shift Time: Sh	Inspector: Smc(10						
Visual Comments Inspection NORMAL or ABNORMAL Visible Emission From Shaker Visible Emission From	Jen	05,12				,	
Inspection NORMAL Or ABNORMAL Visible Emission From Shaker Visible Emission From	Shift: 1 st Shift or 2 nd Sh	nift Ti	me: 5	00;			
Visible Emission From	aunit	Inspection NORMAL or	{		Comments		
		nor	too see and the se	•			
		nor	**************************************				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTAT	IONS			
Inspector: 12				
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	ind	5:00AM		
THE SECOND SECOND	Visual Inspection NORMAL Or ABNORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			
		į		

• Visible inspection must be performed during hormal daylight operations and during the part of operations that would normally be expected to cause the greatest e

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		P				
Inspector: Smc/KO:				;	1.4.4	7 - 4 21	
Date of Inspection: 500	6			·		1	,
Shift: (18) Shift or 2 nd Sh	ılft Ti	me:	5,00	-			
	Visual Inspection <u>NOR</u> MAL or ABNORMAL	And the second s		Comments			
Visible Emission From Shaker	nor						
Visible Emission From Discharge Conveyor System	noe						
		1		1			

Visible inspection must be performed during hormal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

background.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the


VISIBLE EMISSION NOTA	TIONS			
Inspector:	PALOMO			
Date of Inspection: 9/6	/12			Y
Shift: 1 st Shift or ^{2nd Sh}	nd	me: 5,00 AM		
- Unit	Visual Inspection <u>NGR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	general state of the state of t		
Visible Emission From Discharge Conveyor System	NOR	**Radium Toryclan (united Street)		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS

VIOLET FILITOOLOUT HOLY	110110		1	
Inspector: Smelko				,
Date of Inspection:	-7,12			1
Shift: 1 st Shift or 2 ^{no} Sh	ift Ti	me: 500		
Onit	Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	nos	·		· · · · · · · · · · · · · · · · · · ·
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTA	ATIONS		_	
Inspector: N LONG				
Date of Inspection: 9/79	12			3
Shift: 1st Shift or Si	rift Ti	me: 5AM		
aUnit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			
Inspector: Ted Compton			,
Date of Inspection: $9/8/1$			ì
Shift: (1 st Shift or 2 nd Shift	Time: 500 PW		-
Unit Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker No. V			
Visible Emission From Discharge Conveyor System			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	
Inspector: RICK PALOMO	
Date of Inspection: 9/8/12	
Shift: 1st Shift or 2nd Shift 2nd Time: 5	OOAM
Visual Inspection NORMAL Or ABNORMAL	Comments
VIsible Emission From Shaker NOR	
Visible Emission From Discharge Conveyor System	

• Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Smello				
Date of Inspection:				i .
Shift: (1st Shift) or 2nd Sh	nift Ti	me: 5		
⊎nit	Visual		Comments	
	Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL			
Visible Emission From Shaker	nok	ACTION ASS.		
Visible Emission From Discharge Conveyor System	nar	No.		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS	, , , , , , ,	4			
Inspector: Rick PA	LOMO					4
Date of Inspection: 9/9	/12				3.	•
Shift: 1 st Shift or ^{2nd} Sh	id	ime:	5:00 AM			
	Visual Inspectio n <u>NOR</u> MAL or <u>ABN</u> ORMAL			Comments		; ;; ; ;;
Visible Emission From Shaker	NOR		***************************************			
Visible Emission From Discharge Conveyor System	NOR					

- Visible inspection must be performed during hormal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS Inspector: OMO Date of Inspection: Shift: 1st Shift or 2nd Shift Time: ########**Unit** Visual Comments Inspection NORMAL or ABNORMAL Visible Emission From Shaker NOK Visible Emission From Discharge Conveyor System NOR

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Smell(0)				
Date of Inspection: SCOT	10,12			1
Shift: 1 st Shift or 2 nd Sh		me: 500		
Unit	Visual		Comments	
	Inspection NORMAL or ABNORMAL			
Visible Emission From Shaker	nor	- - securing		
Visible Emission From Discharge Conveyor System	noR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector: RICK P	TLOMO			
Date of Inspection: 9/11	/12			1
Shift: 1 st Shift or 2 nd Sh	ift 2nd Tin	me: 51.00AM		
	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	NOR	in the second se		
Visible Emission From Discharge Conveyor System	NOR			

• Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTA	ATIONS			1			
Inspector: Smelko					*		
Date of Inspection:						<u>*</u>	,
JEP!	11,12			4.		-•	
Shift: 1st Shift or 2nd Sh	ifft Ti	me: 500)				
Junit Visible Emission From Shaker	Visual Inspection NORMAL Or ABNORMAL				Comments		
Visible Emission From Discharge Conveyor System	1000						
Districtings Services System	11015					 	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: 2nd Shift Shift: 1st Shift or Time: Unit Visual Comments Inspection NORMAL or... ABNORMAL Visible Emission From Shaker NOR Visible Emission From Discharge Conveyor System

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTA	ATIONS			
Inspector: Smelko				
Date of Inspection: Sept	12,12			7
Shift: 1st Shift or 2nd Sh	ift Ti	me: 5.00		
alumit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	nor	araditoning.		
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS					
Inspector: LICA V	HOMO			. •		
Date of Inspection: 9/13/	/12				· ·	
Shift: 1 st Shift or 2 nd Sh	· 2119	me: 5 dd A				
-Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Co	mments		************
Visible Emission From Shaker	NOR	and the second s				
Visible Emission From Discharge Conveyor System	NOR	Andrew Marie and Andrew Andrew Marie and Andrew Andrew Marie and Andrew Marie and Andrew Marie and Andrew Ma				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		
Inspector: Smelko	e e	
Date of Inspection: Sept. 13 / 12		1
Shift: (St Shift or 2 nd Shift Time: 500		
Unit Visual Inspection	Comments	
NORMAL		

or <u>ABN</u>ORMAL

nof

nok

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 2/10/09

Visible Emission From Shaker

Visible Emission From Discharge Conveyor System


VISIBL	EE	MISS	ION N	ATO!	CIONS
--------	----	------	-------	------	-------

AIOIDEL FINIOCIOIA IAO IA	1110110		_	
Inspector: Smello		,		
Date of Inspection: Sept	4,12			
Shift: 1st Shift or 2nd Sh	ılft Ti	me: 5,00		
aUmit	Visual Inspection NGRMAL Or ABNORMAL		Comments	
Visible Emission From Shaker	nor	_		
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	
Inspector: HCMPALOMC	
Date of Inspection: 0/14/12	1
Shift: 1st Shift or 2std Shift ST Time: 5,00 M	1
Unit Visual Inspection	Comments:
NORMAL	
Or ABNORMAL	
Visible Emission From Shaker	
Visible Emission From	
Discharge Conveyor System NOR	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.




VISIBLE EMISSION NOTA	ATIONS				
Inspector:	MITC				
Date of Inspection:	7-15-12				ì
Shift: 1 st Shift or 2 nd Sh	·	ime: 6:00cm			
-Unit	Visual		Comments		
	Inspection <u>NORMAL</u> or ABNORMAL				
Visible Emission From Shaker	Noc			· · · · · · · · · · · · · · · · · · ·	
Visible Emission From	. / .				
Discharge Conveyor System	Nol				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS											
Inspector: Smelko					~							
Date of Inspection: Sept	13,12									ì		
Shift: (St Shift) or 2 nd Sh		me: 5 cd)					-				
aUnit .	Visual Inspection					. :: : : :	Comments		• •	• •		
	<u>NOR</u> MAL			* . **				· · · · · · .		· · .· · . ·	:	:
	ABNORMAL										٠.	
Visible Emission From Shaker	nor	~ 1			:							
Visible Emission From Discharge Conveyor System	nor			. :	1 -							

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTA	ATIONS		•	
Inspector:	am ot an			
Date of Inspection: 9/16/	112			Y Y
Shift: 1 st Shift or (2 ^{no})Sh		me: 560AW		
aunit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nov			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS	,	1				
Inspector: Smc(Ko						* .	
Date of Inspection: Sept	16,12					**	·
Shift: (1st Shift) or 2nd Sh	ift Tim	ie:	500				
	Visual Inspection NORMAL or: ABNORMAL	And the state of t		Comments	,		:: :::
Visible Emission From Shaker	nor	-					
Visible Emission From Discharge Conveyor System	nor	1					

- Visible inspection must be performed during hormal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Rick Af	tlomo			
Date of Inspection: 9/17	112			<i>Y</i>
Shift: 1 st Shift or 2 nd Sh	fift 2nd Ti	me: 5:00Am		
aunit	Visual Inspection NORMAL Or ABNORMAL		Comments	
Visible Emission From Shaker	NOR	Print Print State Community		
Visible Emission From Discharge Conveyor System	NOR	. And the second		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS			
Inspector: Smello			``````````````````````````````````````
Date of Inspection: Sept 17,12	<u> </u>	4	
Shift: (1 st Shift or 2 nd Shift 1	Time: SOO	Comments	,
Unit Visual Inspection <u>NOR</u> MAL or		Comments	
Visible Emission From Shaker			
Visible Emission From Discharge Conveyor System			

Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D 1 12 Daily Visible	Emissions (Stack SDS 04)

	1 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		And the second s
SIBLE EMISSION NOTATIONS			_
SIRI E EMISSION NOTATIONS			
SIBLE EINIGO			
CHROLO: KV 10 V		Comments	
Timensetion: Sent 1/11 Tim	ne: 500		
To Shirt		William Charles	
InSPEC			
NORMAL Or			
ABNORMAL Chaker OCIC			
From Shaker NOR			
Visible Emission From Shaker 00K	Name !		
Visible Emission From MOD			. La expecte
Visible Emission From Visible Emission From System			uset would normally be exp
Dischargo	Ì	ext of op	erations that would normally be expecte
	*	and during the participant	wew of an object little

Visible inspection must be performed uring normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

background.

SIBLE EMISSION NOTATIONS
spector: Smello
Jate of Inspection: Sept 18 Time: 5:00 Comments
Shift: (19 Shift)
Unit NoRMA
ABNORMAL ABNORMAL
Visible Emission From Shaker $\rho \rho$
Form
Visible Emission From Discharge Conveyor System OUNCE OUNCE Discharge Conveyor System OUNCE D

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

 Onacity is a measure of the degree to which emissions reduce the transmission of light and allowed the transmissions.
- cause the greatest emissions.

 Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: RICK	PALOMe	·		
Date of Inspection:	8/12			Y
Shift: 1 st Shift or 2 nd Sh	2nd	me: 5;00AM	_	
Junt	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	And the second s		
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AISIBLE EMISSION NOTATIONS	
Inspector: Ted Compton	
Date of Inspection: 9/19/12	
Shift: 1 st Shift or (2 ^{no} Shift Time:	
Inspection NORMAL or ABNORMAL	Comments
Visible Emission From Shaker No.	
Visible Emission From Discharge Conveyor System	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations (Stack SDS 04) VISIBLE EMISSION NOTATIONS MALOME Inspector: 5:00Am Comments Date of Inspection: 2nd Shift Shift: 1st Shift or Visual Inspection NORMAL MENORMAL NOR Visible Emission From Shaker Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to Visible Emission From NOK Discharge Conveyor System cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	D.1.12 Daily Visible Emissions Notation (Stack SDS 04)	
ISIBLE EMISSION NOT		
apactor: Ome Inspection:	Shift Time: 500 comments Visual Inspection NORMAL	
/Isible Emission From Shak Visible Emission From Discharge Conveyor System	ABNORMAL ABNORMAL NOR NOR	ally be expected
Visible inspectio	n must be performed during normal daylight operations and during the part of operest emissions. easure of the degree to which emissions reduce the transmission of light and obscious of the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the transmission of light and obscious the degree to which emissions reduce the degree to the de	rations that would normally bure the view of an object in the
opacity is a me background.	asure of the dog.	
Revised 2/10/09		
Keyise		

	una Emissio	ns Notations Per Lustin	•
	D.1.12 Daily Visible Emissio	tack SDS 04)	
VISIBLE EMISSIO	The second of th		
Date of Inspection:	Sect 19 12 Time: 500	Comments	
Shift: (1st Shift o	Visual Inspection NORMAL		
Visible Emission i	ABNORMAL NOR		
Visible Emission f Discharge Conve		and the part of	operations that would normally be expected to
Visible cause Opaci hackg	inspection must be performed during normal day the greatest emissions. ty is a measure of the degree to which emissions round.	light operations and during the parties and control reduce the transmission of light and c	bscure the view of an object in the

background.

cause the greatest emissions.

. Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Continues A.	Notations Per Each Des
	Wigible Emissions Notation (SDS 04)
	D.1.12 Daily Visible Emissions Notations Per Each D. (Stack SDS 04)
	TATIONS
VISIBLE EMISSION	1 PACOMO
Inspector	17.2
Date of Inspection:	21/12 Time: 5:00AM Comments
Date of more	shirt 2nd
Shift: 1 Shift or	Visual
THE	EXTEND Inspection
	TO THE OF THE PARTY OF THE PART
	ABNORMAL
Visi∎le Emission Fro	
Visitio	
Visible Emission Fro Discharge Conveyor	em NOR
Discharge Con-	of organions that would not the
	and during the part of upon an object in the
	amal daylight operations and obscure the view of and obscure the
	the performed during hornian the transmission of light
va-ible in	don must be possible and some reduce the state of the sta
visible th	tion must be performed during hormal daylight operations and during the part of operations that would normally be expected to atest emissions. The degree to which emissions reduce the transmission of light and obscure the view of an object in the measure of the degree to which emissions reduce the transmission of the degree to the transmission of the degree
onacity	Modes
backgro	
1	

	/isible Emissions Notations Per Laci (Stack SDS 04)
D.1.12 Daily V	(Stack about
	A Company of the comp
VISIBLE EMISSION NOTATIONS	
ISIBLE EMISSION INC.	
Specion Offic 100	e. 5.00 comments
and Shift	e: 5100
Shift: (181 Shift) Of Visual	
Inspection NoRMAL Or	
ABNORMAL	
Visible Emission From Shaker NO /L	
Visible Emission From Visible Emission From Visible Emission From Visible Emission From	
Visible Emission From Discharge Conveyor System O()	that would normally be expected to
District	during the part of operations that we
	normal daylight operations and during
rection must be performed	during normal daylight operations and during the part of operations that would normally be expected to during normal daylight operations and during the part of operations that would normally be expected to during normal daylight operations and during the part of operations that would normally be expected to during normal daylight operations and during the part of operations that would normally be expected to
Visible inspections. Visible inspections emissions. cause the greatest emissions.	O Mylch Augges
Opacity is a measure background.	
packetosii	
1	
,*	
Revised 2/10/09	

AISIBLE EMISSION MON	ATIONS 1			· · · · · · · · · · · · · · · · · · ·	
Inspector:	CR PAC	Olic	1		
Date of Inspection:	122/12				3
Shift: 1 st Shift or 2 nd Sh	1lft 2nd	Time: 5100AM			
Junit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Commente	i	:
Visible Emission From Shaker	NOR				
Visible Emission From Discharge Conveyor System	NOR		;		
	,		,		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	D.1.12 Daily Visible Emissions Notations Per Each Day (Stack SDS 04)		
· · · · · · · · · · · · · · · · · · ·	TATIONS		
Date of Inspection	on: 9/22/12 Time: 5 pm Comments	i	
Shift: 1st Shift	Visual Inspection NORMAL		
Visible Emission	on From Shaker /VAC		
Visible Emission Discharge Con	on From Non-		,

Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the

background.

VISIBLE EMISSION NOTA	AHONS				
Inspector: Smelko					
Date of Inspection:	22 10			,	°t.
0000	10/12		1		
Shift: (1 st Shift) or 2 nd Sh	•	me: 500			
Unit	Visual		g + 1	Comments	*
	Inspection				
	NORMAL		and his sign of		
					`
	<u>ABN</u> ORMAL				· ·
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	nor	-matterpara-			
((

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.






D.1.12 Daily Visible Emissions Notations Per Each Dayny... (Stack SDS 04)

VISIBLE EMISSION NOTA	ATIONS					
Inspector:	7					
	melon					
Date of Inspection: 9/22/	12				` <u>`</u>	
Shift: 1 st Shift or (2 nd)SI	nift Ti	ime: 500 AM				
- Unit	Visual			Comments	,	*
	Inspection <u>NGR</u> MAL					1.3
	ABNORMAL			PARINT -	:	
Visible Emission From Shaker	Nov	differential intercognical literature in the second commonwhele values of the second commonwhele values of the	SECURIORIE CONTINUE DE CONTINU			
Visible Emission From		- description of the second of	Andrew Control of the			
Discharge Conveyor System	Nov	The state of the s				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to
- cause the greatest emissions.

 Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	Waible Emissions Notations	
	D.1.12 Daily Visible Emissions Notations Per Luci	
VISIBLE EMISSION NOTA		
Inspector: Smello		
Bata of Inspection: Sect	24, 12 Time: 5'00 comments	
or 2 3	iff the state of t	
Shift: (1° Shift)	Inspection NoRMAL or	
	ABNORMAL]
Visible Emission From Shake	nor	·
Visible Emission From Discharge Conveyor System	NOR	cted to
Dischars	f operations that would normally be over	
	the toperations and during the part of operation of an object in the	
	the performed during normal daylight operations and during the part of operations and obscure the view of an object in the	
Visible inspection	must be performed during normal daylight operations and during the part of operations and obscure the view of an object in the st emissions.	A Section 1
onacity is a med	must be performed during normal daylight operations and during the part of operations that would normally be expeted the performed during normal daylight operations and during the part of operations that would normally be expended to the transmission of light and obscure the view of an object in the sure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the sure of the degree to which	The second secon
Visible inspection cause the greater Opacity is a mean background.	must be performed during normal daylight operations and during the part of operations that would normal daylight operations and during the part of operations that would normal daylight operations and during the part of operations that would normal daylight operations and during the part of operations that would normal daylight operations and during the part of operations that would not be a supplied to the control of the part of operations that would not be a supplied to the control of the part of operations that would not be a supplied to the control of the part of operations that would not be a supplied to the control of the part of operations that would not be a supplied to the control of the part of operations that would not be a supplied to the control of the part of operations that would not be a supplied to the control of the c	
onacity is a med	must be performed during normal daylight operations and during the part of uperations and obscure the view of an object in the st emissions. Sure of the degree to which	
onacity is a med	must be performed during normal daylight operations and during the part of operations and obscure the view of an object in the st emissions. Sure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the	
onacity is a med	must be performed during normal daylight operations and during the part of upor an object in the st emissions. Is a sure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the strength of the degree to which emissions reduce the transmission of light and obscure the view of an object in the strength of the degree to which emissions reduce the transmission of light and obscure the view of an object in the strength of the degree to which emissions reduce the transmission of light and obscure the view of an object in the strength of the degree to which emissions reduce the transmission of light and obscure the view of an object in the strength of the degree to which emissions reduce the transmission of light and obscure the view of an object in the strength of the degree to which emissions reduce the transmission of light and obscure the view of an object in the strength of the degree to which emissions are strength of the degree to which emissions are the strength of the degree to which emissions are strength of the degree to the degre	
onacity is a med	must be performed during hormal daylight operations and during the part of operations and object in the st emissions. Sure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the	
onacity is a med	must be performed during hormal daylight operations and during the part of operations and obspure the view of an object in the strength of the degree to which emissions reduce the transmission of light and obspure the view of an object in the strength of the degree to which	
onacity is a med		
onacity is a med		
onacity is a med		



(833)	while Emissions Notations Per Each
مريق	D.1.12 Daily Visible Emissions Notations Per Each D. (Stack SDS 04)
VISIBLEE	WISSION NOTATIONS Sweet CO
Date of Ins	action: 5co+ 25, 5 Time: 5,00 PM Comments
3000	Morita Inspection Norwal
Violate E	Nission From Shaker NOR
Visible E Dischart	nission From Conveyor System
	Visible inspection must be performed during normal daylight operations and during the part of operations that would now of an object in the cause the greatest emissions. Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the hackground.
•	Visible inspection must be performed as the greatest emissions. Cause the greatest emissions. Cause the greatest of the degree to which emissions reduce the greatest emissions reduce the greatest emissions.
	background.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	ations Per Each Du,
,40	D.1.12 Daily Visible Emissions (Stack SUS 04)
VISIBLE EMISS	ON NOTATIONS CONVACOMO
Date of Inspection	Time: 5'.00 A-M Comments
Visible Emission	Inspection NORMAL ABNORMAL From Shaker NORMAL
VIsible Emission Discharge Conv	Inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to the greatest emissions. Inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to the greatest emissions. Inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to the greatest emissions. Inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to the greatest emissions. Inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to the greatest emissions. Inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to the greatest emissions. Inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to the greatest emissions.
Onac	inspection massions. the greatest emissions to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to which emissions reduce the day to the degree to the day to th

Inspection: 9 28 12 Shift: 1st Shift or 2nd Shift 2nd Time: 5 00 Am Wisual Comments Inspection Normal ABNORMAL Visible Emission From Shaker Discharge Conveyor System Normal	VISIBLE EMISSION NOTATIONS		
Shift: 1 st Shift or 2 nd Shift 200 Time: 500 A/M Visual Comments Inspection NORMAL or ABNORMAL Visible Emission From Shaker Visible Emission From	Inspector: RICK: FALOM	Colored Services	
Visible Emission From Visible Emission From Visible Emission From	1120112	,	
Inspection NORMAL Or ABNORMAL Visible Emission From Shaker Visible Emission From	<u> </u>	me: 5/0dAM	
Visible Emission From	Inspection <u>N©R</u> MAL or	karan kalan ang karang karang kalang kal	
	Visible Emission From Shaker Narc	**	

Visible inspection must be performed during hormal daylight operations and during the part of operations that would normally be expected to

cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		the second of the second	
Inspector: Smelto			·
Date of Inspection:		, ,	Y Y
Shift: (1 ⁵ Shift) or 2 nd Shift	Time: 5,00		
Visual Inspectio Normal or ABNORMA		Comments:	
Visible Emission From Shaker 100 R			
Visible Emission From Discharge Conveyor System \(\sum_{\text{O}} \ightarrow \ightarrow \text{Q}	- Augustus-		

• Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS	·* .				
Inspector: Smelko	±2 1.	,				$\frac{\partial}{\partial x} = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} \right) = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} \right) = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} \right) = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} \right) = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} - \frac{\partial}{\partial x} \right) = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} - \frac{\partial}{\partial x} \right) = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} - \frac{\partial}{\partial x} - \frac{\partial}{\partial x} \right) = \frac{\partial}{\partial x} \left(\frac{\partial}{\partial x} - \frac{\partial}{\partial x} -$
Date of Inspection: Sept	28.12				•	1
Shift: As Shift or 2nd Si	nlift O T	lme:	5.00Pm			
	Visual Inspection NORMAL or ABNORMAL			Comments		
Visible Emission From Shaker	nor	_				
Visible Emission From Discharge Conveyor System	nor					

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	
Inspector: - RICK PALOM C	$\mathcal{A} = \{ \frac{S}{S} : S = \frac{S}{S} \}$
Date of Inspection: 9 24/12	1
Shift: 1st Shift or 2nd Shift 2nd Time: 5100AM	
Visual Comments Inspection NORWAL Or ABNORMAL	
Visible Emission From Shaker NOR	
Visible Emission From Discharge Conveyor System NOR	

- Visible inspection must be performed during hormal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Date of Inspection: 9/29/12 Shift: 1st Shift or 2st Shift Time: 500 PM Visual Inspection NORMAL Visible Emission From Shaker Visible Emission From	VISIBLE EMISSION NOTATIONS.	the second of the second of the second	· ·	
Shiff: (1st Shiff or 2nd Shiff Time: 500 PM) Shiff: (1st Shiff or 2nd Shiff Time: 500 PM) Visual: Comments Inspection NORMAL: Or ANSNORMAL Visible Emission From Shaker Visible Emission From Discharge Conveyor System				
Visual Comments Inspection NORMAL Or. ABNORMAL Visible Emission From Discharge Conveyor System Discharge Conveyor System	7/29/12			W. J. Y.
Visitat Inspection (NORMAL) Or ABNORMAL Visible Emission From Discharge Conveyor System	Shift: (1 st Shift or 2 nd Shift	Time: 500 PM		
Visible Emission From Discharge Conveyor System	Inspection NORMAL or ABNORMAL		Commente	
Discharge Conveyor System	Visible Emission From Shaker Nor			
	Discharge Conveyor System		· · · · · · · · · · · · · · · · · · ·	

Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the

background.

Revised 2/10/09

新加斯·西斯特尼·西西斯 人名英格兰 (1985)

VISIBLE EMISSION NOTATIONS

Inspector Smelle	V. 1 deat.	- 1				
Date of Inspection: Scot	30,12				177. 1	-
Shift: (1 st Shift) or 2 nd St		lme:	500			
	Visual Inspection NORMAL Or ABNORMAL			Comments		: :: ::
Visible Emission From Shaker	nor					
Visible Emission From Discharge Conveyor System	nor	1				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 2/10/09

的特别是特别的企业。 为你们是这些